

# SUPERTALENT ULTRADRIVE GX FIRMWARE RELEASE NOTES

2.5" SATA-II SOLID STATE DRIVE



Copyright ©, Property of Super Talent Technology. All rights reserved. The information and specification provided in this document should be used for comparative analysis and reference purposes. The contents of this document are subject to change without prior notice.

**1.0 FIRMWARE VERSION 1819 (AFTER 1571)**

Release Date: 10/15/09

Serial Numbers: xxxxxxxx-xFBX-xxxxxxx

Change Log:

1. Updater runs out of DOS instead of Windows
  - 1.1 Added ATA8 ACS2 TRIM Support
  - 1.2 SATA Rx SSC is turn off by default, Now Rx and Tx SSC both off
  - 1.3 IDENTIFY word 69 bit 14 is cleared (Non deterministic trim)
  - 1.4 IDENTIFY word 60-61 are changed (User addressable logical sectors for LBA28)
  - 1.5 FPDMA error return code was not adequate
  - 1.6 SMART related changes were made (BBM error log was removed)
  - 1.7 SATA error handling code was enhanced
  - 1.8 Added paired page calculation for Micron 34nm MLC NAND
2. Bug Fix: Fixed a bug in error handling in Set Multiple mode command
3. Bug Fix: Fixed a bug that caused 1.5Gbps diagnostic failure
4. Bug Fix: SMART related bugs were fixed
5. Bug Fix: Toshiba 43nm NAND has address hole and previous firmware couldn't handle it.
6. Bug Fix: SMART related bugs were fixed. (MLC Max PE count was displayed as 100K)
7. Bug Fix: Current ATA security state was not reflected in IDENTIFY information.
8. Bug Fix: Performance boost routine reused the recently used block and it did harm to wear leveling.
9. Bug Fix: During SATA protocol, abrupt OOB made Barefoot hang.

10. Bug Fix: End user update failed between 1571 and 1711.
11. Bug Fix: In bad block management, wrong number of free blocks is used and it led to timeout and hang.
12. Bug Fix: After STANDBY\_IMMEDIATE, most host controllers wait for OOB reply only for 100ms. Sometimes Barefoot firmware couldn't answer to COMRESET because FTL initialization took longer time. This bug caused Windows Sleep/Hibernate test failure.
13. Bug Fix: Various read fail scenario were found with FTL simulation.
14. Barefoot ECO chip support code was added.
15. More NAND ICs supported

## 2.0 FIRMWARE VERSION 1571

Release Date: 5/28/09

Serial Numbers: xxxxxxxx-xDIX-xxxxxxx

Change Log:

1. Updater runs out of DOS instead of Windows
  - 1.1 Enables fixing of failed firmware installation characterized by "Yatapdong Barefoot ROM ATA"
  - 1.2 Enables firmware updates on Apple Mac
  - 1.3 Updater no longer requires AHCI mode
  - 1.4 Updater compatibility instability with nVidia chipsets fixed
2. Bug Fix: ATA Security command now working in AHCI mode
3. Bug Fix: When receiving invalid SMART subcommands, abort is now sent to host to minimize long delays
4. Bug Fix: Corrected values of some SMART attribute data initialization

5. Bug Fix: ATA Security Command now returning correct values
6. Enables life expectancy calculation
7. Other internal bug corrections

### 3.0 FIRMWARE VERSION 1370

Release Date: 5/14/09

Serial Numbers: xxxxxxx-xCIX-xxxxxxx

Change Log:

1. Adds support for TRIM command
2. Firmware Update now preserves serial number
3. Bug Fix: Apple Mac Pro sleep/wake test now passes
4. Other internal bug corrections